## Brightwell, Leola

From: Turner, Nardina

**Sent:** Thursday, March 10, 2016 8:20 AM

To: Saskowski, Ronald

Subject: FW: R4 LIMS Sample Log for Project 13-0182, WorkOrder C130703

Attachments: C130703 WKO 02 11 13 1119 pdf

From: R4SampleCustody

Sent: Monday, February 11, 2013 10:49 PM
To: Johnston, Shelby < Johnston. Shelby @epa.gov>

Cc: Colquitt, Debbie <Colquitt.Debbie@epa.gov>; Wasko, Mike <wasko.mike@epa.gov>; Turner, Nardina

<Turner.Nardina@epa.gov>; smithdm@bv.com; ProutyS@bv.com
Subject: R4 LIMS Sample Log for Project 13-0182, WorkOrder C130703

Attached is a detailed work order report, in Adobe Acrobat PDF format, containing information about samples and their scheduled analyses for the following Project:

**Project Number:** 13-0182

Project Name: Southeastern Wood Preserving
City: Canton County: Madison State: MS

## Samples in the following categories have been submitted for analysis:

Dioxin (DIO)

Please review the attached report and notify our Sample Control Coordinator by e-mail at R4SampleCustody@epa.gov if you have any questions, concerns, or if you notice any errors.

## \*\*CONFIDENTIALITY NOTICE\*\*

This e-mail is intended only for the use of the specific individual(s) to whom it is addressed. If you are not an intended recipient of this e-mail, you are hereby notified that any use, dissemination or copying of this e-mail or the information contained in it or attached to it is unauthorized. If you have received this e-mail in error, please immediately notify us by reply e-mail to R4LIMS@epa.gov and then delete this message.

### WORK ORDER

### C130703

Printed: 2/11/2013 11:19:25AM

# US-EPA, Region 4, SESD, QAS

Superfund Remedial (302DD2, 303DD2) Client: Project Number: 13-0182 Contract Lab Case: 43272

Southeastern Wood Preserving - SJOHNS11 Acct # Location: 303DD2041LLA01 Canton Madison MS Project:

Project Leader: Johnston, Shelby Date Due: 02 03 13 (21 day TAT)

Received By: Colquitt, Debbie Date Received: 01 13 13 00:00 Colquitt, Debbie Logged In By: Date Logged In: 02 11 13 11:18

CL x Dioxin % Moisture

CL Dioxin

CL x Dioxin Scan

D.A.R.T. Project ID: <u>13-0015</u>

Program/Activity: RI

Site/Waterbody: SOUTHEASTERN WOOD PRESERVING, INC

(110007646002)

Analysis	Due	TAT	Comments	
C130703-01 001_10 / SW MD No:	'P001 [Soil/Subsurface Soil] S D No: "2N" CAPE	-		
A = Costruct Lab Gangde				
CL Dioxin	02 03 13 00:00	21	from F2L	
C130703-02 002_12 / SW MD No:	'P002   Soil / Subsurface Soil   S D No: 72N4   CAPE			
A = Costruct Lide Hargsle				
CL Dioxin	02 03 13 00:00	21	from F2L	
MD No:	WP002 [Soil / Subsurface Soil ] D No: 72N5 CAPE	•	0	
A = Contract Lab Sample				
CL Dioxin		21	from F2L	